



Office & Laboratory : 32/41, South Side of G. T. Road, UPSIDC Industrial Area, Ghaziabad - 201 009, UP, INDIA,
Contact No. : 9711159210, 9711159427 E-mail : email@ekopro.in, ekoproengineers@gmail.com, website : www.ekopro.in

TEST REPORT**Water Sample Analysis**

Test Report No. : EK0/EV-WA/106/130417 Issue Date 20/04/2017

Issued To Design Co (DC)
Lakari, Fazlpur,
Delhi Road, Moradabad,
(U.P.)

Sample Description Drinking Water
Sample Drawn on 12/04/2017
Sample Drawn by EPEPL (Mr. Alok Kumar)
Sample Received on 13/04/2017
Sampling Location From Water Cooler Ground Floor Building- II
Sampling Plan & Procedure SOP-W/66
Sample Quantity 500 ml
Environmental Condition Normal
Analysis Duration 13/04/2017 To 19/04/2017
Remark (if any) NA

RESULTS

S.No.	PARAMETER	Test Methods	Result	Units	IS: 10500 : 2012 (Limits)*	
					Acceptable	Permissible
1	Total Coliform	IS : 1622 : 1981	< 2	MPN/100 mL	Shall not be detectable in 100ml sample	-
2	E.coli	IS : 1622 : 1981	Absent	Per 100 mL	Shall not be detectable in 100ml sample	-

* For details pl see IS : 10500-2012.

End of Report

Notes :

- The results given above are related to the tested sample, as received & mentioned parameters.
The customer asked for the above tests only.
- This test report will not be generated again, either wholly or in part, without written permission of the Laboratory.
- This test report will not be used for any publicity/legal purpose.
- This test samples will be disposed off after two weeks from the date of issue of test report, unless until specified by the customer.
Sample received for biological tests will be destroyed after 7 days from the date of issue of test report.
- Responsibility of the Laboratory is limited to the invoiced amount only.

For EKO PRO ENGINEERS PVT. LTD

Authorized Signatory

